

DEEP CLEAN XTREME – All Purpose Cleaner Product Data Sheet

PRODUCT DESCRIPTION

DEEP CLEAN XTREME is an effective, heavy duty, all-purpose cleaner designed to clean and remove dirt, grime, grease and other potentially harmful organic and inorganic contaminants from most surfaces. It breakdowns grease, oils and other organics for easy removal by wiping or washing. Scrubbing then washing with water is recommended for heavy buildup or for "xtreme" cleaning of surfaces. It can be used on any surface that is not damaged by water or moisture. DEEP CLEAN XTREME is easily sprayed on then wiped off with a wet or dry cloth or paper towel.

DEEP CLEAN XTREME is water-based and fully biodegradable.

FOR USE ON

- Plexiglass and sneeze guards will not cause fogging or clouding
- Counter tops, walls and ceramic tiles
- Bathrooms, public use areas and garbage cans
- Many car surfaces
- Doors, handles, knobs
- Metal, glass and stainless steel surfaces
- Equipment, machines and parts
- Most hard, non-porous surfaces
- Boats and marine surfaces
- Some soft or porous surfaces
- Always test for substrate suitability.

DIRECTIONS TO CLEAN SMALL AREAS:

Decant from large container into trigger spray bottle. Spray onto soiled surface. Rinse and wipe clean with paper towel or damp cloth. For heavily soiled surfaces, let applied product dwell on surfaces for several minutes. Rinse and wipe clean with paper towel or damp cloth.

Use in well ventilated areas. Do not inhale or swallow. Avoid contact with skin, eyes and delicate surfaces.

LARGE AREA COVERAGE:

250 square feet / 1 gallon

Large areas can be cleaned using pump sprayer / garden sprayer.

APPLICATION METHODS

- By spray (trigger sprayer or pump/garden sprayer)
- Horizontal areas: Product can be poured on surface and distributed evenly over the surface by squeegee method.
- If distributing over large areas with squeegee ensure liberal coverage

SITE CONDITIONS & PREPARATION for LARGE APPLICATION AREAS

- Apply in weather above freezing.
- ALWAYS DO A TEST PATCH TO ENSURE SUBSTRATE SUITABILITY.
- Ensure all areas not to be treated are properly protected (wipe/wash off overspray)
- Remove loose dirt and debris prior to application.

DWELL TIME

- Spray on wipe off
- Heavily soiled surfaces may need up to 10 minutes or longer.

REMOVAL

- Wipe off or wash off small surface areas
- Pressure washing is effective for large area cleaning projects.
- When needed, a vacuum system can be used to pick up used product.
- ALWAYS check and comply with local disposal regulations.

CLEAN-UP

- Ensure all unused product is stored in closed containers.
- DEEP CLEAN XTREME is biodegradable but always follow with local disposal regulations.

PHYSICAL PROPERTIES

Color Clear Physical State Liquid Foaming Capacity Very Low Odor Mild/Low 10.0 pН VOC's < 1% Solubility in Water Complete Freeze/Thaw Stability Very Stable

Always use this product according to Manufacturer's Directions

For further information contact the Manufacture. SAFETY & PERSONAL PROTECTIVE EQUIPMENT

- Do not ingest, swallow or inhale.
- Avoid contact with eyes flush well with water if contact occurs
- Avoid contact with skin if this occurs wash off well with water.
- If clean
- ing large areas and applying by pump sprayer in confined spaces or on large surface areas, use standard protective equipment gloves, glasses and mask.